

APPENDIX B –PHOTOS OF JULY 12 TO 14, 2004, SITE VISIT



Photo B-1: July 12, 2004, Grouting on Right Abutment



Photo B-2: July 12, 2004, Grouting on Right Abutment



Photo B-3: July 12, 2004, Grout Mixer



Photo B-4: July 12, 2004 Right Abutment Core Trench Excavation



Photo B-5: July 12, 2004, Diversion Pipe under Cofferdam



Photo B-6: July 12, 2004 Waste Rock Pile at Adit



Photo B-7: July 12, 2004, Waste Rock from Adit Excavation