

APPENDIX C –PHOTOS OF FEBRUARY 21 TO 24, 2005 SITE VISIT



Photo C-1: February 21/22, 2004, Overview of Coffer Dam and Foundation Excavations



Photo C-2: February 21/22, 2004, Right Abutment Core Trench and Foundation



Photo C-3: February 21/22, 2004, Right Abutment Core Trench Foundation Prior to Dental Concreting



Photo C-4: February 21/22, 2004, Left Abutment excavation



Photo C-5: February 21/22, 2004, Left Abutment Lower Core Trench w Grout Cap and Low Level Outlet Pipe Trench



Photo C-6: February 21/22, 2004, Grouting Drill Rig on Left Abutment



Photo C-7: February 21/22, 2004, Grouting Mixer and Pump



Photo C-8: February 21/22, 2004, Downstream Valley Base with Instrument Trench



Photo C-9: February 21/22, 2004, Main Drain - Drain Rock on Filter Layer



Photo C-10: February 21/22, 2004, Main Drain – Showing Filter Placement on Sides of Drain Rock



Photo C-11: February 21/22, 2004, Segregation of Filter Material Observed on Live Stockpile



Photo C-12: February 21/22, 2004, Low Fines Segregated Filter Material



Photo C-13: February 21/22, 2004, Excavation Into Bedrock for Monitoring Weir



Photo C-14: Initial Core Placement for Saddle Dam on East Flank



Photo C-15: February 21/22, 2004, Adit Waste Rock Pile